

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 128077

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080189-5

RECEIVED FROM		DATE REC'D. 2-1-57		P. O. NO. 64303		VENDOR PACKING SLIP NO. 55919	
CHARGE TO	CONTRACT CODE NO. 222	DRAWING NUMBER 000000	DWG. DASH OR STANDARD PART NO. 20031	DWG. REV. 0	LOT NO. 0	CLASS NUMBER 00	OPER. NUMBER 00
QUANTITY RECEIVED 6	DRAWING NO. AND DESCRIPTION			QUANTITY		REMARKS	
	730145-20002 BRACKET 1 1/2 IN 152			ACCEPTED 6		REJECTED	
	UNLESS MOUNTING TIME						
	P.O.P. NUMBER 73031						
RECEIVED BY	INSPECTED BY	DATE 4/1/57		REJECTS RETURNED ON SHIP. MEMO NO.			

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No. 128108

2941 E. COLORADO ST., PASADENA 8, CALIF.

RECEIVED FROM		DATE REC'D. 1-16-57		P. O. NO.		VENDOR PACKING SLIP NO.	
CHARGE TO	CONTRACT CODE NO. 222	DRAWING NUMBER 00000	DWG. DASH OR STANDARD PART NO. 20005	DWG. REV. 00	LOT NO. 0	CLASS NUMBER 00	OPER. NUMBER 00
QUANTITY RECEIVED 2	DRAWING NO. AND DESCRIPTION			QUANTITY		REMARKS	
	730354 GEAR SHAFT 1 1/2 IN			ACCEPTED 2		REJECTED	
	MATERIAL P.O. 65834						
RECEIVED BY	INSPECTED BY	DATE 1/16/57		REJECTS RETURNED ON SHIP. MEMO NO.			

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080189-5